

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director

OLENE S. WALKER Governor

OGM

GAYLE F. McKEACHNIE

Lieutenant Governor

Representativ	es Present During the Inspection:	
Company	Rusty Netz Environmental Coordin	ator

Dana Dean Environmental Scientist III

Karl Houskeeper Environmental Scientist III

Inspection Report

Permit Number:	C0070035		
Inspection Type:	PARTIAL		
Inspection Date:	Wednesday, January 28, 2004		
Start Date/Time:	01/28/2004 10:00:00 AM		
End Date/Time:	01/28/2004 12:00:00 PM		
Last Inspection:	Thursday, December 18, 2003		

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: <u>Clear, ~Temperature 30 Deg. F</u> InspectionID Report Number: <u>163</u>

> Accepted by: pgrubaug 01/28/2004

Permitee: SUNNYSIDE COGENERATION ASSOCIATES
Operator: SUNNYSIDE COGENERATION ASSOCIATES

Site: SUNNYSIDE REFUSE & SLURRY

Address: PO BOX 159, SUNNYSIDE UT 84539

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages		Mineral Ownership	Types of Operations
310.00	Total Permitted	☐ Federal	
202.00	Total Disturbed	☐ State	Surface
	Phase I	\Box County	Loadout
	Phase II	✓ Fee	Processing
	Phase III	Other	✓ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Divison Orders, and amendments:

Inspector's Signature:	Date	Wednesday, January 28, 2004

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining



Permit Number: C0070035 Inspection Type: PARTIAL

Inspection Date: Wednesday, January 28, 2004

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENT

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	✓		✓	
3.	Topsoil	✓			
4.a	Hydrologic Balance: Diversions	✓			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓			
4.c	Hydrologic Balance: Other Sediment Control Measures	✓			
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives		✓		
6.	Disposal of Excess Spoil, Fills, Benches	✓			
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓		✓	
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.	a Roads: Construction, Maintenance, Surfacing				
16.	b Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070035 Inspection Type: PARTIAL

Inspection Date: Wednesday, January 28, 2004

Page 3 of 3

2. Signs and Markers

The mine ID sign has been knocked down. The sign is covered with mud and has been placed on the backside of a temporary sign. The operator made arrangements during the inspection to have the sign reestablished and cleaned.

4.d Hydrologic Balance: Water Monitoring

The approved permit indicates that baseline water monitoring be done for one quarter every fifth year before permit renewal for all of the monitoring sites. This item was not done prior to the last renewal as identified in the joint inspection with the Division Hydrologist. The operator committed to performing baseline monitoring for all of the sites during the first quarter of 2004. Fourth quarter 2003 water monitoring has been entered and uploaded into the EDI website.

7. Coal Mine Waste, Refuse Piles, Impoundments

The trailer identified on the previous inspection located on the refuse pile has been removed as instructed.

The smoker identified on the previous inspection has been taken care of. The refuse pile appeared stable with no visible hazards.